

March 18, 2022

Att: Justin Seeney, PE & John Montgomery, PE  
Village of Port Chester  
Building Department  
222 Grace Church Street  
Port Chester, NY 10573

Re: Stormwater Management – Engineering Review  
34 Bush Avenue  
Block: 02 Lot: 17

We respectfully submit a full set of revised drawings for the above-referenced application. Please note the following in response to comments received by Justin Seeney, PE & John Montgomery, PE.:

1. Please refer to C-200.00. The Percolation Test methodology and results has been provided.
2. Please refer to C-200.00. A table has been provided indicating the depth of the percolation test at specified locations.
3. Please refer to C-200.00. A table has been provided including a note indicating, “ No groundwater and/or bedrock observed at or 3’ below test location.”

Respectfully Submitted,



Shahin Badaly  
PE 095887